

DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt Governor Ted Stewart **Executive Director**

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

801-359-3940 (Fax)

Exploration: Complete: Partial: X Inspection Date & Time: 2/23/95 7:00am-1:00pm Date of Last Inspection: _

James W. Carter Division Director 801-359-3940 (Fax) 801-538-5319 (TDD) Mine Name: <u>Crandall Canyon Mine</u> County: <u>Emery</u> Permit Number: <u>ACT/015/032</u> Permittee and/or Operator's Name: Genwal Coal Company Business Address: P. O. Box 1201, Huntington, Utah 84528 Surface Prep. Plant Type of Mining Activity: Underground XXX Other Company Official(s): Larry Johnson State Officials(s): Stephen J. Demczak Federal Official(s): Weather Conditions: Warm 40's Existing Acreage: Permitted- 2165.42 Disturbed- 5.55 Regraded- .. 5 Seeded- .. 5 Bonded- 5.55 Increased/Decreased: Permitted-____ Disturbed-___ Regraded-___ Seeded-___ Bonded-___ Status: __Exploration/_XXX_Active/__Inactive/__Temporary Cessation/__Bond Forfeiture Reclamation (__Phase I/__Phase II/ Final Bond Release/__Liability__

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	<u>[]</u>	[X]	
2.	SIGNS AND MARKERS	\Box	\Box	$\overline{\square}$	$\overline{\square}$
3.	TOPSOIL	$\overline{\square}$	\Box	ĹĴ	
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]	\Box	[X]	<u>L_1</u>
b.	SEDIMENT PONDS AND IMPOUNDMENTS	$\overline{[X]}$	\Box	[<u>X]</u> [X] []	\Box
c.	OTHER SEDIMENT CONTROL MEASURES	$\overline{\square}$	\Box	\Box	\Box
d.	WATER MONITORING		П	\Box	\Box
e.	EFFLUENT LIMITATIONS	\Box	\Box	\Box	\Box
5.	EXPLOSIVES	\Box	\Box		
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	\Box	\Box	\Box	\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	\Box	\Box		\Box
8.	NONCOAL WASTE	\Box	\Box	\Box	
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES		\Box		
10.	SLIDES AND OTHER DAMAGE	\Box	\Box	\Box	\Box
11.	CONTEMPORANEOUS RECLAMATION	\Box	\Box		\Box
12.	BACKFILLING AND GRADING	\Box	\Box		
13.	REVEGETATION	\Box	\Box		\Box
14.	SUBSIDENCE CONTROL	\Box	\Box		· []
15.	CESSATION OF OPERATIONS	\Box	\Box		\Box
16.	ROADS:				
a.			\Box		
b.		\Box			
	OTHER TRANSPORTATION FACILITIES	\Box	\Box		
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	\Box	\square		
19.	AVS CHECK (4th Quarter-April, May, June)(date) []			Ĺ
20.	AIR QUALITY PERMIT	\Box			
21	RONDING & INSURANCE	F 1	[]	ſĨ	f 1



INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 2/23/95

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

The Mining and Reclamation Permit of the operator and the PFO were compared against each other. It was found that several maps and text needed to be updated in the PFO's copy of the permit. Operator copied current text and implemented into plan. Maps will be implemented as soon as possible.

4a. DIVERSIONS -

The diversions were being cleaned out during and prior to the inspections. Water was flowing through the ditches and sediment was being cleaned out.

b. SEDIMENT PONDS -

The sediment pond was not discharging during the inspection but possibly could, unless the water is pumped back into the mine. The permittee has permission to pump water into the mine.

The sediment pond showed no signs of hazardous conditions existing.

Note: this inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas , and Mining.

Copy of this Report:

Mailed to: <u>Larry Johnson (Genwal)</u> Donna Griffin (OSM)

Given to: Joe Helfrich (DOGM) Filed to: Price Field Office

Date: February 28, 1995

Inspector's Signature:

Stephen J. Demezak